Company Listing Submitted Variable V			UST Service Provider List	(All)		
Fax (866) 425-2661	Company			·	Area of state conducts work	
Black Mountain, NC 28711 Website advancedemvironmentalsolutions.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Control Prevention Equipment Operability Check: No Contaminent Surry Testing: Yes Statistical Invertor, Nanocialisation Services: Yes Control Prevention Equipment Testing: No Spill Prevention Equipment Testing: Yes UST Internal Inspections: No Tark Tightness Testing: No Tark Tightness Testing: Yes UST Internal Inspections: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation Prevention Equipment Testing: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Installation - Complete Systems: No UST System Removal: No UST	Advanced Environmental Solutions, LLC		Phone (828) 664-9822		Coastal (East of I-95): Yes	
Compliance Testing and Monitoring UST Equipment Service Contractors Ves Contractors Ves Ve	P.O. Box 1426		Fax (866) 425-2661		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring Vas Contractors Vas Contractor Testing: Yas Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Culibration: No Containment Sump Testing: Yas Statistical Ventory Reconciliation Services: Yas Corresion Protection Design Experts: No Spill Prevention Equipment Testing: Yas Vas Va	Black Mountain, NC 28711		Waterita advanced environmental edutions and		Mountains (West of I-77): Yes	
Automatic Line Leak Detection Testing: Yes Statistical Ventory Reconcilation Services: Yes Statistical Ventory Reconsiliation Services: Yes Statistical Ventory Reconsilia			website <u>advancedentiforimentalsolutions.com</u>			
Containment Sump Testing: Vas Statistical Iventory Recombilation Services: No Spill Prevention Equipment Testing: Vas Spill Bucket Installation Servicing: No Spill Bucket Installation Servicing: No Spill Bucket Installation Paperis: No Spill Bucket Installation - Corher: No Spill Bucket Installation - Corher: No UST Equipment Installation - Corher: No UST Equipment Repair: No UST Equipment Mustallation: No UST System Installation: No UST Equipment Installation: No UST System Installation: No UST	Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yas UST Equipment Inspections (Integrity Assessments): No UST Internal Lining Inspections (Integrity Assessments): No UST Equipment (Portablation - Complete System Repairs: No UST Internal Lining Inspections (Integrity Assessments): No UST Equipment (Portablation - Complete Systems: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment (Portablation: No UST Equipment Operability Check: No UST Compliance Consultants: No UST Piping Symp Installation: Complete Systems: No UST Piping Symp Installation: Complete Systems: No UST Equipment Operability Checks: No UST Equipment Verification: No UST Equipment (Verification: No UST Equipment (Verification: No UST Equipment): No UST Equipment (Verification: No UST Equipment (Verification: No UST Equipment (Verification: No UST Equipment): No UST Equipment (Verification: No UST Equipment (Verification: No UST Equipment): No UST Equipment (Verification: No UST Equip	Automatic Line Leak Detector Testing:	<u>Yes</u>		No		No
Corrosion Protection System Repairs: No Tank Tightness Testing: Yes UST Internal Inspections: No UST internal Inspections: No UST internal Inspections: No UST internal Inspections: No UST prigning Services: No Other: UST Equipment Operability Check: No UST internal Inspections: No UST Prigning Sump Installation: No UST System Installat			· · · · · · · · · · · · · · · · · · ·	<u>Yes</u>		No
Corrosion Protection System Tasting: Yas UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation: Complete Systems: No UST System Installation: No UST Installation System Installation: No UST Installation System Installation: No UST Installation System Installation: No UST System Installation: No UST System Installation: No UST System Installation: No UST Installation: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation: No UST S	• .	No		<u>Yes</u>		
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Installation - Complete Systems: No UST Equipment Polarization - Complete Systems: No UST Equipment Polarization - Complete Systems: No UST Equipment Polarization: No UST System Removal: No UST System		No		<u>Yes</u>		No
Leak Detection Monitoring Services: No Other: Vgs		<u>Yes</u>		No		No
Line Tightness Testing: Yes UST System Removal: No Other:		No		No		No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: Company	_	No	Other:			
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No Other: No UST Equipment Verification: No Other:	Line Tightness Testing:	<u>Yes</u>				No
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other: No Other: No Other: No Other: No Other:	Er	nvironme	ntal Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu No Other: Oil and Solvent Recycling: No Other: Oil and Solvent Recycling: No Other: Oil and Solvent Recycling: No Other: No Other: No Other: No Other: Oil and Solvent Recycling: No Other: No Ot	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Listing Submitted 9/2/2015 Area of state conducts work Coastal (East of I-95): Yes Coastal (East of I-95): Yes Recompany Recompany Contral (West of I-77): Yes Website Contral (West of I-77): Yes Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Leak Detector Monitoring Leak Detection Monitoring Services: No UST Equipment Installation Servicing: No Leak Detection Equipment Operability Check: No UST Equipment Installation - Other: No UST Equipment Installation: No UST System Removal: No Other:	Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Company Listing Submitted 9/2/2015 Area of state conducts work	Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Advanced Environmental Solutions, LLC Phone (828) 664-9822 P.O. Box 1426 Black Mountain, NC 28711 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: Yes Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Overfill Prevention Equipment Testing: Yes Overfill Prevention Equipment Testing: Yes Statistical Iventory Reconciliation Services: Yes UsT Equipment Installation Servicing: No Spill Bucket Installation Repair: No Spill Bucket Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No Other:	Oil and Solvent Recycling:	No	Other:			
Advanced Environmental Solutions, LLC Phone (828) 664-9822 P.O. Box 1426 Black Mountain, NC 28711 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: Yes UST Equipment Installation Repair: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: Yes UST Internal Lining Inspections: No UST Equipment Operability Check: No UST System Installation - Other: No UST System Installation - Complete Systems: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No UST Equipment Removal: No UST System Remov	Soil and Water Testing Lab:	No				
P.O. Box 1426 Black Mountain, NC 28711 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Statistical Iventory Reconciliation Services: Yes Statistical Iventory Reconciliation Services: Yes Overfill Prevention Equipment Operability Check: No Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: Yes Statistical Iventory Reconciliation Services: Yes Statistical Iventory Reconciliation Services: Yes Spill Bucket Installation Repair: No Spill Prevention Equipment Testing: Yes UST Equipment Installation Servicing: No Corrosion Protection System Repairs: No Tank Tightness Testing: Yes UST Internal Inspections: No UST Internal Inspections: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No Other: No Other: No Other: No UST Compliance Consultants: No UST System Removal: No Other: N	Company		Listing Submitted	9/2/2015	Area of state conducts work	
Black Mountain, NC 28711 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: Yes Statistical Iventory Reconciliation Services: Yes Spill Bucket Installation Servicing: No Spill Prevention Equipment Testing: Yes Spill Bucket Installation Repair: No Corrosion Protection Design Experts: No Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Repair: No UST Compliance Consultants: No UST Equipment Repair: No UST System Removal: No UST System Removal: No UST System Removal: No Other:	Advanced Environmental Solutions, LLC		Phone (828) 664-9822		Coastal (East of I-95): Yes	
Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: Yes Spill Bucket Installation Servicing: No Spill Prevention Equipment Testing: Yes Spill Bucket Installation Servicing: No Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Repair: No UST System Installation - Other: UST System Installation - Complete Systems: No UST System Removal: No	P.O. Box 1426		Fax (866) 425-2661		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: Yes Statistical Iventory Reconciliation Services: Yes Spill Bucket Installation Repair: No Tank Tightness Testing: Yes UST Equipment Installation - Other: No UST Internal Inspections (Integrity Assessments): No UST System Repairs: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: No UST Sy	Black Mountain, NC 28711		. ,			
Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: Yes Statistical Iventory Reconciliation Services: Yes Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Other: No Other: No Other:			Website		mountains (west of 1-17). Tes	
Containment Sump Testing: Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Corrosion Protection System Repairs: No Tank Tightness Testing: Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Repair: No UST System Installation: No UST System Removal: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other: No Other: No Other: No Other: No Other:	Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Repairs: No Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: N	Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other:	Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: No UST System Installation - Complete Systems: No UST Systems Installation - Complete Systems Installation - Complete Systems Inst	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other: UST Piping/Sump Installation: No UST System Removal: No Other:	Corrosion Protection System Testing:	<u>Yes</u>		No		No
Line Tightness Testing: Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Oil and Solvent Recycling: No Other:	Leak Detection Equipment Operability Check:	No	- · · · · · · · · · · · · · · · · · · ·	No		No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No UST Equipment Verification: No Oil and Solvent Recycling: No Other:	Leak Detection Monitoring Services:	No	Other:			
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Other:	Line Tightness Testing:	<u>Yes</u>				No
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Er	nvironme	ntal Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: No Other:	Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
		No	Waste Disposal and Treatment:	No		
Soil and Water Testing Lab:	Oil and Solvent Recycling:	No	Other:			
Soli and water Testing Lab. INC	Soil and Water Testing Lab:	No				

		UST Service Provider List	(All)		
Company		Listing Submitted	· /	Area of state conducts work	
AES of Greenville		Phone (252) 758-3311		Coastal (East of I-95):	Yes
PO Box 59		Fax (252) 481-5814		Central (West of I-95 and East of I-77):	Yes
Greenville, NC 27835				Mountains (West of I-77):	Yes
		Website www.aes-nc.com		,	
Comp	oliance T	esting and Monitoring		UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironme	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	12/9/2015	Area of state conducts work	
Barrett PetroWorks LLC		Phone (828) 729-5861		Coastal (East of I-95):	No
809 Hillsfarm St. NE		Fax		Central (West of I-95 and East of I-77):	Yes
Lenoir, NC 28645				Mountains (West of I-77):	
		Website		mountaine (cross or cray).	
Comp	oliance T	esting and Monitoring		UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	<u>Yes</u>
		Other:		UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes	Other: ental Service Firms		UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Yes		No	UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No	ental Service Firms UST Compliance Consultants: UST Equipment Verification:	No No	UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Err Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes No No	ental Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:		UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No	ental Service Firms UST Compliance Consultants: UST Equipment Verification:	No	UST System Removal:	<u>Yes</u>

		UST Service Provider List (AII)		
Company		Listing Submitted	9/8/2015	Area of state conducts work	
Blue Ridge Environmental Services, Inc.		Phone (704) 482-2111		Coastal (East of I-95): No	
2315 Kings Rd. Ext.		Fax (704) 482-4335		Central (West of I-95 and East of I-77): Yes	
Shelby, NC 28152	W	/ebsite		Mountains (West of I-77): Yes	
0.000				HOT Feederment Coming Contractors	
		ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	9/10/2015	Area of state conducts work	
Company Bunnell-Lammons Engineering Inc.		Listing Submitted Phone (828) 277-0100	9/10/2015	Area of state conducts work Coastal (East of I-95): No	
		Phone (828) 277-0100	9/10/2015	Coastal (East of I-95): No	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200			9/10/2015	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Bunnell-Lammons Engineering Inc. 130 Oval Road	W	Phone (828) 277-0100	9/10/2015	Coastal (East of I-95): No	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704		Phone (828) 277-0100 Fax (828) 277-0110	9/10/2015	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704		Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com	9/10/2015 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp	oliance Test	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Compa	oliance Test No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 277-0100 Fax (828) 277-0110 Vebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (828) 277-0100 Fax (828) 277-0110 /ebsite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (828) 277-0100 Fax (828) 277-0110 Pebsite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC		Phone (919) 757-7901		Coastal (East of I-95): Yes	
8005 Clear Brook Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615				Mountains (West of I-77): Yes	
	1	Website CapeLookoutEnv.com			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/23/2015	Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC		Phone (919) 757-7901		Coastal (East of I-95): Yes	
8005 Clear Brook Drive				· · · · · · · · · · · · · · · · · · ·	
Raleigh, NC 27615		Fax		Central (West of I-95 and East of I-77): Yes	
	1	Website CapeLookoutEnv.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No		No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No				No
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List ((All)		
Company		Listing Submitted	9/24/2015	Area of state conducts work	
Cardno, Inc.		Phone (919) 871-0999		Coastal (East of I-95): Yes	
2725 E. Millbrook		Fax (919) 871-0335		Central (West of I-95 and East of I-77): Yes	
Suite 121 Raleigh, NC 27604				Mountains (West of I-77): Yes	
Kaleigii, NO 27004	W	ebsite <u>www.cardno.com</u>			
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: N	Ю
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: N	10
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	· ·	10
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: N	10
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		Ю
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		10
Leak Detection Monitoring Services:	No	Other:			10
Line Tightness Testing:	No				<u>'es</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	4###### ###	Area of state conducts work	
Company Cedar Rock Environmental, P.C.		Listing Submitted Phone (336) 376-0394	*#######	Area of state conducts work Coastal (East of I-95): Yes	
Cedar Rock Environmental, P.C. 807 Bullard Lane		Phone (336) 376-0394	4#######	Coastal (East of I-95): Yes	
Cedar Rock Environmental, P.C.			*#######	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cedar Rock Environmental, P.C. 807 Bullard Lane		Phone (336) 376-0394	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Coastal (East of I-95): Yes	
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253	W	Phone (336) 376-0394 Fax (336) 376-0395	4#######	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253	W	Phone (336) 376-0394 Fax (336) 376-0395 ebsite www.cedarrockenvironmental.com	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comp	W oliance Test	Phone (336) 376-0394 Fax (336) 376-0395 ebsite www.cedarrockenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Line Leak Detector Testing:	W oliance Test	Phone (336) 376-0394 Fax (336) 376-0395 ebsite www.cedarrockenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison of Compar	W Dliance Test No No	Phone (336) 376-0394 Fax (336) 376-0395 Lebsite www.cedarrockenvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Wolliance Test No No No No	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Note that Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Woliance Test No No No No	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Note that the service Contractors Note that the service Contractors	10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No No	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Note that Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Note that Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 376-0394 Fax (336) 376-0395 Lebsite www.cedarrockenvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanure	No N	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	10 10 10 10
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 376-0394 Fax (336) 376-0395 Pebsite www.cedarrockenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	10 10 10 10

		UST Service Provider List ((AII)		
Company		Listing Submitted	` '	Area of state conducts work	
C-First, Inc.		Phone (540) 777-9111		Coastal (East of I-95): Yes	
1119 Beaumont Rd.		Fax (540) 777-9112		Central (West of I-95 and East of I-77): Yes	
Roanoke, VA 24019	W	ebsite www.c-firstinc.com		Mountains (West of I-77): Yes	
Comr		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
Er	nvironmenta	I Service Firms		Other: Wayne Dispensers and Verifond	ne POS
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
- The Control of the					
Company		Listing Submitted	9/9/2015	Area of state conducts work	
Company			9/9/2015		
		Phone (910) 574-4748	9/9/2015	Coastal (East of I-95): Yes	
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd.			9/9/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Charles Broadfoot & Associates, Inc. PO Box 53730		Phone (910) 574-4748	9/9/2015	Coastal (East of I-95): Yes	
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305	W	Phone (910) 574-4748 Fax 253-681-05	9/9/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305	W	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com	9/9/2015 Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comp	W Dliance Testi	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing:	W pliance Testi Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check:	Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	W Dliance Testi Off Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	W Diliance Testi Off Off Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	W Dliance Testi Off Off Off Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Wind District Tests Off Off Off Off Off Off Off Off Off Of	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Off Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wind District Tests Off Off Off Off Off Off Off Off Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Williance Testi Off Off Off Off Off Off Off Off Off Of	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Off Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Williance Testi Off Off Off Off Off Off Off Off Off Of	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Off Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wind off off off off off off off off off of	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Off Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Off Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	Off Off Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Off Off Off Off Off
Company Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Off	Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	Off Off Off Off Off Off Off Off	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Off Off Off Off Off

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Cobb Environmental & Technical Services, Inc).	Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street, Tupelo, MS 38804 Tupelo, MS 38804	W	ebsite www.cobbenv.com		Mountains (West of I-77): Yes	
		ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing: Corrosion Protection Design Experts:	<u>Yes</u> No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No You	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection Design Expens. Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	<u>Yes</u> No	UST Equipment Installation - Other:	<u>Yes</u> Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing:	<u>res</u> Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/23/2015	Area of state conducts work	
Cohesion, Inc.		Phone (919) 233-8626		Coastal (East of I-95): Yes	
5216 Yates Mill Pond Road Raleigh, NC 27606		Fax (919) 233-8909		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27000	W	ebsite www.cohesion-inc.com		Mountains (West of I-77): Yes	
		ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No No	Tank Tightness Testing:	No No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST Equipment Repair: UST System Installation - Complete Systems:	No No
Leak Detection Equipment Operability Check. Leak Detection Monitoring Services:	No	Other:	NO	UST Piping/Sump Installation:	No
Line Tightness Testing:	No	Outer.		UST System Removal:	Yes
<u> </u>		Il Service Firms		Other:	
			NI-		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No No		
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	UST Equipment Verification:	No No		
Oil and Solvent Recycling:	<u>Yes</u> No	Waste Disposal and Treatment: Other:	No		
Soil and Water Testing Lab:		Other.			
Soil and Water Leging Lab.	No				1

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Cohesion, Inc.	F	Phone (919) 233-8626		Coastal (East of I-95): Yes	
5216 Yates Mill Pond Road		Fax (919) 233-8909		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27606	147	Later and the state of the same		Mountains (West of I-77): Yes	
	We	bsite www.cohesion-inc.com		, ,	
Comp	liance Testir	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/26/2015	Area of state conducts work	
CROMPCO, LLC		Phone (800) 646-3161		Coastal (East of I-95): Yes	
1815 Gallagher Road				· · · · · · · · · · · · · · · · · · ·	
Plymouth Meeting, PA 19462		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Yes	
	We	bsite www.crompco.com		Mountains (West of I-77): Yes	
Comp	liance Testir	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	JST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	JST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:		JST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List (AII)		
Company		Listing Submitted		Area of state conducts work	
CSM Environmental, PLLC		Phone (336) 367-4145		Coastal (East of I-95): No	
PO Box 99		Fax (336) 367-4772		Central (West of I-95 and East of I-77): Yes	
Boonville, NC 27011	W	lebsite www.csmenvironmental.com		Mountains (West of I-77): Yes	
				1107.5	
		ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: UST System Removal:	No No
Line Tightness Testing:	No			Other:	No
	nvironmenta	I Service Firms		outer.	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/4/2015	Area of state conducts work	
		Listing Submitted Phone (919) 596-0470	9/4/2015	Area of state conducts work Coastal (East of I-95): Yes	
Company EMS Environmental, Inc. 117 South Hoover Road			9/4/2015		
Company EMS Environmental, Inc.		Phone (919) 596-0470 Fax (919) 596-0578	9/4/2015	Coastal (East of I-95): Yes	
Company EMS Environmental, Inc. 117 South Hoover Road	W	Phone (919) 596-0470	9/4/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703		Phone (919) 596-0470 Fax (919) 596-0578	9/4/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703		Phone (919) 596-0470 Fax (919) 596-0578 /ebsite www.emsenv.com	9/4/2015 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp	oliance Test	Phone (919) 596-0470		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Test No	Phone (919) 596-0470 Fax (919) 596-0578 Vebsite www.emsenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (919) 596-0470 Fax (919) 596-0578 Vebsite www.emsenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (919) 596-0470 Fax (919) 596-0578 Lebsite www.emsenv.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 596-0470 Fax (919) 596-0578 Vebsite www.emsenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (919) 596-0470 Fax (919) 596-0578 Lebsite www.emsenv.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 596-0470 Fax (919) 596-0578 Vebsite www.emsenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 596-0470 Fax (919) 596-0578 Vebsite www.emsenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 596-0470 Fax (919) 596-0578 Lebsite www.emsenv.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 596-0470 Fax (919) 596-0578 Lebsite www.emsenv.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (919) 596-0470 Fax (919) 596-0578 Lebsite www.emsenv.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 596-0470 Fax (919) 596-0578 Pebsite www.emsenv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List	(All)		
Company		Listing Submitte		Area of state conducts work	
Enviro Consulting		Phone (704) 721-0101		Coastal (East of I-95): Yes	
531 Pitts School Road NW		Fax (704) 721-0102		Central (West of I-95 and East of I-77): Yes	
Suite D Concord, NC 28027				Mountains (West of I-77): Yes	
Concord, NC 20027	W	/ebsite www.envirocorp.net			
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other: UST Lining I	nstallation	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 9/10/2015	Area of state conducts work	
Environmental Compliance Services of NC, PC	;	Phone (704) 583-2711		Coastal (East of I-95): Yes	
13504 South Point Boulevard, Unit F	;				
	•	Phone (704) 583-2711 Fax (704) 583-2744		Central (West of I-95 and East of I-77): Yes	
13504 South Point Boulevard, Unit F					
13504 South Point Boulevard, Unit F Charlotte, NC 28273	W	Fax (704) 583-2744		Central (West of I-95 and East of I-77): Yes	
13504 South Point Boulevard, Unit F Charlotte, NC 28273	W	Fax (704) 583-2744 Vebsite www.ecsconsult.com	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
13504 South Point Boulevard, Unit F Charlotte, NC 28273	W Oliance Test	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Company Automatic Line Leak Detector Testing:	W pliance Test No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	W Dliance Test No No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Williance Test No No No Yes	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No Yes Yes	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes Yes Yes	Fax (704) 583-2744 Vebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No Yes Yes Yes No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No Yes No Yes No Yes No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No Yes No Yes No Yes No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Eclipse -Total Tank Compliance	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No Yes No Yes No Yes No Yes No	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Eclipse -Total Tank Compliance	No No No No Services	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
13504 South Point Boulevard, Unit F Charlotte, NC 28273 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No Yes Yes No Yes No Yes No Yes No Yes No Yes No Trinonmenta	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Eclipse -Total Tank Compliance al Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No Services Yes No Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes Yes No Yes No Yes No Yes No Yes No Yes No Trinonmenta	Fax (704) 583-2744 /ebsite www.ecsconsult.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Eclipse -Total Tank Compliance al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No Services Yes No Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List	(All)		
Company		Listing Submitte		Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27410				Mountains (West of I-77): Yes	
		Website www.envirotrac.com		mountains (West of 177).	
Com	pliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
The state of the s					
Company		Listing Submitte	d	Area of state conducts work	
Company Envirovation Geologic Consulting and Mappir	ng, PC	Listing Submitter Phone (828) 406-0772	d	Area of state conducts work Coastal (East of I-95): No	
Envirovation Geologic Consulting and Mappir PO Box 3425	ng, PC	Phone (828) 406-0772	d ########	Coastal (East of I-95): No	
Envirovation Geologic Consulting and Mappir	ng, PC		d	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Envirovation Geologic Consulting and Mappir PO Box 3425	ng, PC	Phone (828) 406-0772	d #############	Coastal (East of I-95): No	
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607		Phone (828) 406-0772 Fax	d	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607		Phone (828) 406-0772 Fax Website www.envirovationconsulting.com	d ######## No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607	pliance Te	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing:	pliance Te	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Te No No	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Te No No No	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Te No No No No No No	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Te No No No No No No	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanure	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Envirovation Geologic Consulting and Mappir PO Box 3425 Boone, NC 28607 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (828) 406-0772 Fax Website www.envirovationconsulting.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Evo Corporation	ļ	Phone (336) 725-5844		Coastal (East of I-95): Yes	
1703 Vargrave Street		Fax (336) 725-6244		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27107	W	ebsite www.evocorp.net		Mountains (West of I-77): Yes	
Come		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:		UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:	<u></u>		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/8/2016	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	
Gastonia, NC 28054					
Castoma, 110 2000 i					
	We	ebsite www.excelengr.com		Mountains (West of I-77): Yes	
	oliance Testi	ebsite www.excelengr.com	No	Mountains (West of I-77): Yes	No
Сотр	oliance Testi No	ebsite www.excelengr.com ng and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ebsite www.excelengr.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ebsite www.excelengr.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Vo revironmental Yes Yes Yes	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo revironmental Yes Yes Yes	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No Ves Yes	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)	
Company		Listing Submitted		Area of state conducts work
Fourstar Petroleum	I	Phone (540) 563-1022		Coastal (East of I-95): Yes
1119 Beaumont Rd.		Fax (540) 362-1802		Central (West of I-95 and East of I-77): Yes
Roanoke, VA 24019	We	ebsite www.fourstarpetro.com		Mountains (West of I-77): Yes
Comr	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: Yes
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: Yes
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: Yes
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other: Yes
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: Yes
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: Yes
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation: Yes
Line Tightness Testing:	No			UST System Removal: Yes
Er	nvironmenta	I Service Firms		Other: Wayne Dispensers and Verifone PO
Emergency Cleanup - Spill/Release:		UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:		Other:		
Soil and Water Testing Lab:	No			
Company		Listing Submitted	9/13/2015	Area of state conducts work
Galloway		Phone (303) 770-8884		Coastal (East of I-95): Yes
Julional		FIIOTE (303) 110-000 -1		
6162 South Willow Drive	l			Central (West of I-95 and East of I-77): Yes
6162 South Willow Drive Suite 320	l	Fax (303) 770-3636		Central (West of I-95 and East of I-77): Yes
6162 South Willow Drive				Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111	We	Fax (303) 770-3636		
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111	We oliance Testi	Fax (303) 770-3636 ebsite www.GallowayUS.com	No	Mountains (West of I-77): Yes
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp	We pliance Testin	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing:	We pliance Testin No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	We Dliance Testin No No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No
6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No
G162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax (303) 770-3636 ebsite www.GallowayUS.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Geological Resources, Inc.		Phone (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28110		Website www.geologicalresourcesinc.com		Mountains (West of I-77): Yes	
Comr	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No		No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		No
Leak Detection Monitoring Services:	No	Other:			No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/9/2015	Area of state conducts work	
GREENWOOD APPLIED SERVICES LLC		Phone (252) 398-6022		Coastal (East of I-95): Yes	
P.O. BOX 238 COLERAIN, NC 27924		Fax (252) 356-2208		Central (West of I-95 and East of I-77): No	
GOLLIVAIN, NO 27324		Website www.greenwoodapplied.com		Mountains (West of I-77): No	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No		No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Landfarm Soil Disposal, MMPE,AFVR, Well	Drilling		
Soil and Water Testing Lab:	No				

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
GREENWOOD APPLIED SERVICES LLC	1	Phone (252) 398-6022		Coastal (East of I-95): Yes	
P.O. BOX 238		Fax (252) 356-2208		Central (West of I-95 and East of I-77): No	
COLERAIN, NC 27924	147	L. M		Mountains (West of I-77): No	
	VV€	ebsite <u>www.greenwoodapplied.com</u>		· · ·	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal: Other:	<u>Yes</u>
Er	nvironmental	I Service Firms		Other.	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Landfarm Soil Disposal, MMPE,AFVR, Well	Drilling		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/17/2015	Area of state conducts work	
HARCO Services LLC	1	Phone (770) 917-8846		Coastal (East of I-95): Yes	
PO Box 2347		Fax (770) 917-0921		Central (West of I-95 and East of I-77): Yes	
Kennesaw, GA 30156		•		Mountains (West of I-77): Yes	
	\\/	- la - ! (meantaine (11001 01111). 100	
	•	ebsite www.harcoservices.com			
Comp		ng and Monitoring		UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	oliance Testi		No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
_	oliance Testi	ng and Monitoring	No No		No No
Automatic Line Leak Detector Testing:	No No	ng and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> No

		UST Service Provider List (AII)		
Company		Listing Submitted		Area of state conducts work	
Highlands Environmental Solutions, Inc.	ı	Phone (919) 848-3155		Coastal (East of I-95): Yes	
8410-D Falls of Neuse Road		Fax (919) 848-4265		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615	***	Later was IIFOtast asset		Mountains (West of I-77): Yes	
	VVe	ebsite <u>www.HESfast.com</u>		· ·	
Comp	oliance Testii	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
•					
Company		Listing Submitted	9/18/2015	Area of state conducts work	
-		Listing Submitted Phone (704) 662-8192	9/18/2015	Area of state conducts work Coastal (East of I-95): Yes	
INENCO, Inc. 132 W. Statesville Ave.	ı		9/18/2015	Coastal (East of I-95): Yes	
Company INENCO, Inc.		Phone (704) 662-8192 Fax (704) 662-8194	9/18/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
INENCO, Inc. 132 W. Statesville Ave.		Phone (704) 662-8192	9/18/2015	Coastal (East of I-95): Yes	
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115	We	Phone (704) 662-8192 Fax (704) 662-8194	9/18/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115	We pliance Testin	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com	9/18/2015 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115	We pliance Testin No	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com Ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing:	We Dliance Testin No No	Phone (704) 662-8192 Fax (704) 662-8194 Phone (704) 662-8194 Phone (704) 662-8192 Phone (704) 662-8194 Pho	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	We Dliance Testin No No No	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (704) 662-8192 Fax (704) 662-8194 Pebsite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No No No No	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (704) 662-8192 Fax (704) 662-8194 Pebsite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 662-8192 Fax (704) 662-8194 Phone inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 662-8192 Fax (704) 662-8194 Pebsite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 662-8192 Fax (704) 662-8194 Phosite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (704) 662-8192 Fax (704) 662-8194 Phosite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 662-8192 Fax (704) 662-8194 Phosite inencoinc.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No Ves Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List	(All)		
Company		Listing Submitte		Area of state conducts work	
J&W Plumbing Inc.		Phone (828) 433-6364		Coastal (East of I-95): No	
PO Box 1686		Fax (828) 433-5534		Central (West of I-95 and East of I-77): No	
118 Stephens Road Morganton, NC 28655				Mountains (West of I-77): Yes	
Morganion, No 20000	V	Vebsite		, ,	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d ########	Area of state conducts work	
Company JGD Associates, Inc.		Phone 4409336825	d	Area of state conducts work Coastal (East of I-95): Yes	
JGD Associates, Inc. 92 Moore Road			d	Coastal (East of I-95): Yes	
JGD Associates, Inc.		Phone 4409336825 Fax	d	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
JGD Associates, Inc. 92 Moore Road	V	Phone 4409336825	d	Coastal (East of I-95): Yes	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012		Phone 4409336825 Fax	d	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012		Phone 4409336825 Fax Vebsite www.jgdpe.com	d ######## No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Comp	oliance Tes	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Company Automatic Line Leak Detector Testing:	oliance Tes No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Cal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone 4409336825 Fax Website www.jgdpe.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

		UST Service Provider List	(AII)	
Company		Listing Submitted	`	Area of state conducts work
Johnson, Spellman and Associates		Phone (770) 447-4555		Coastal (East of I-95): Yes
350 Research Court		Fax		Central (West of I-95 and East of I-77): Yes
Suite 130 Peachtree Corners, GA 30092				Mountains (West of I-77): Yes
reachtree Comers, GA 30092		Website www.jsace.com		
Comp	liance Te	esting and Monitoring		UST Equipmment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other: System design services - Eng	ineering	UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Er	vironme	ntal Service Firms		Other: System design services - Engineering
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company		Listing Submitted	10/5/2015	Area of state conducts work
Law Petroleum, Inc.		Phone (704) 573-3535		Coastal (East of I-95): Yes
11025 Arlington Church Road				
Charlotte, NC 28227		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes
		Website		Mountains (West of I-77): Yes
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: Yes
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: Yes
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair: Yes
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems: Yes
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: Yes
Line Tightness Testing:	<u>Yes</u>			UST System Removal: Yes
Er	nvironme	ntal Service Firms		Other:
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Martin & Slagle Geo Sciences, P.A.		Phone (828) 669-3929		Coastal (East of I-95): No	
P.O. Box 1023		Fax (828) 669-5289		Central (West of I-95 and East of I-77): Yes	
24 Lookout Terrace Black Mountain, NC 28711	W	debsite martinandslagle.com		Mountains (West of I-77): Yes	
Comp	liance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
	110				
Company		Listing Submitted	4#######	Area of state conducts work	
			4#######		
Company		Phone (757) 420-2520	########	Coastal (East of I-95): Yes	
Company McCallum PC			*#######	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Company McCallum PC 1808 Hayward Avenue		Phone (757) 420-2520	4#######	Coastal (East of I-95): Yes	
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320	w	Phone (757) 420-2520 Fax (757) 424-2874	4#######	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320	w	Phone (757) 420-2520 Fax (757) 424-2874 (ebsite www.mccallumtestinglabs.com	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comp	W liance Testi	Phone (757) 420-2520 Fax (757) 424-2874 Pebsite www.mccallumtestinglabs.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing:	W Iliance Testi No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	W bliance Testi No No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W voliance Testi No No No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wolliance Testi No No No No No No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	W viliance Testi No No No No No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wolliance Testi No No No No No No	Phone (757) 420-2520 Fax (757) 424-2874 Pebsite www.mccallumtestinglabs.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wollance Testi No No No No No No No No	Phone (757) 420-2520 Fax (757) 424-2874 Pebsite www.mccallumtestinglabs.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wollance Testi No No No No No No No No	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (757) 420-2520 Fax (757) 424-2874 Pebsite www.mccallumtestinglabs.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (757) 420-2520 Fax (757) 424-2874 Lebsite www.mccallumtestinglabs.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LI Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted	9/4/2015	Area of state conducts work	
MECO, Inc. of Florence		Phone (910) 223-0020		Coastal (East of I-95): Yes	
316 Raymond Street		Fax (910) 223-0022		Central (West of I-95 and East of I-77): Yes	
Fayetteville, NC 28301		, ,		Mountains (West of I-77): No	
	W	ebsite <u>www.mecoflorence.com</u>		mountains (vost of 177). The	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	110		
Soil and Water Testing Lab:	No	0.1101.			
		Listing Colomitted	0/20/2015	Avec of state conducts work	
Company		Listing Submitted	9/29/2015	Area of state conducts work	
National Tank Monitor, Inc.		Phone (800) 643-8265		Coastal (East of I-95): Yes	
P.O. Box 940 Vilonia, AR 72173		Fax (501) 796-3981		Central (West of I-95 and East of I-77): Yes	
viiona, rav 72170	W	ebsite www.nationaltankmonitor.com		Mountains (West of I-77): Yes	
		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
				1	

		UST Service Provider List (All)		
Company		Listing Submitted	·	Area of state conducts work	
Nationwide Construction Group		Phone (810) 533-2416		Coastal (East of I-95): Yes	
53861 Gratiot Ave		Fax		Central (West of I-95 and East of I-77): Yes	
Chesterfield, MI 48051				Mountains (West of I-77): Yes	
	V	/ebsite			
Com	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other: General Contracting & New Fuel Station Cons	truction	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	. No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/27/2015	Area of state conducts work	
NC PETROLEUM & CONVENIENCE MARKETE	RS	Phone (919) 782-4411		Coastal (East of I-95): Yes	
7300 GLENWOOD AVE.		Fax (919) 872-4414		Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27612		1 dx (313) 072 4414			
	V	/ebsite <u>WWW.NCPCM.ORG</u>		Mountains (West of I-77): Yes	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other: UST ENGINE	ERING		
Soil and Water Testing Lab:	No				
				I .	

		UST Service Provider List	(AII)		
Company		Listing Submitte		Area of state conducts work	
Nova Consulting Group, Inc.		Phone (704) 258-5196		Coastal (East of I-95): Yes	
442 South Main Street		Fax		Central (West of I-95 and East of I-77): Yes	
Suite # 7 Davidson, NC 28036				Mountains (West of I-77): Yes	
Davidson, NC 28036		Website http://novaconsulting.com/		mountains (wost of 177).	
Comp	liance To	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 8/31/2015	Area of state conducts work	
Oil Equipment Sales & Service Co., Inc.		Phone (757) 543-3596		Coastal (East of I-95): Yes	
P. O. Box 5096		Fax (757) 543-6196		Central (West of I-95 and East of I-77): No	
4331 Bainbridge Blvd.		(101) 010 0100		Mountains (West of I-77): No	
Chesapeake, VA 23324		Website		Wouldains (West of 1-77). No	
Comp	liance To	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	vironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List (AII)		
Company		Listing Submitted		Area of state conducts work	
Petroleum Equipment and Service, Inc.		Phone (704) 335-8801		Coastal (East of I-95): Yes	
4125 Sinclair Street		Fax (704) 342-1672		Central (West of I-95 and East of I-77): Yes	
PO Box 1949 Denver, NC 28037	W	ebsite www.petroleumequipment.net		Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/27/2015	Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.		Phone (252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502		Fax (252) 237-5507		Central (West of I-95 and East of I-77): No	
711 S. Goldsboro St.				Mountains (West of I-77): No	
Wilson, NC 27894	W	ebsite <u>www.peswilson.com</u>		mountains (west of 1-17). No	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling: Soil and Water Testing Lab:	No No	Other:			

		UST Service Provider List (All)		
Company		Listing Submitted	· /	Area of state conducts work	
Petroleum Service & Calibration, Inc.		Phone (704) 489-1671		Coastal (East of I-95): Yes	
7973 Vista View Drive		Fax (704) 489-1672		Central (West of I-95 and East of I-77): Yes	
Sherrills Ford, NC 28673		,		Mountains (West of I-77): No	
		Website www.petroleumtanktesting.com			
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/2/2015	Area of state conducts work	
PGP Services, LLC		Phone (704) 619-1528		Coastal (East of I-95): Yes	
1949 Candlewick Drive		Fax (803) 802-2441		Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29715		Fax (603) 602-2441			
		Website		Mountains (West of I-77): Yes	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
				1	

		UST Service Provider List ((All)		
Company		Listing Submitted		Area of state conducts work	
Pinnacle Environmental Management Support	, Inc.	Phone (954) 977-3775		Coastal (East of I-95): Yes	
1100 Park Central Boulevard South, Suite 3600		Fax (866) 209-4401		Central (West of I-95 and East of I-77): Yes	
Pompano Beach, FL 33064	We	ebsite www.pinnacleems.com		Mountains (West of I-77): Yes	
Comr		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:		UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other: Trust Fund Claims Preparation	& Mgmt		
Soil and Water Testing Lab:	No	·	Ū		
Company		Listing Submitted	10/5/2015	Area of state conducts work	
Practical Environmental Solutions, PC		Phone (910) 790-8265		Coastal (East of I-95): Yes	
PO Box 12590		Fax (866) 411-8265		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28405		1 ax (000) 411-0203			
	We	ebsite www.oil-tank.com		Mountains (West of I-77): No	
Comp		ebsite www.oil-tank.com ng and Monitoring		Mountains (West of I-77): No UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	oliance Testir		No		No
	oliance Testir	ng and Monitoring	No No	UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing:	oliance Testin No No	ng and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Precision Tank Service		Phone (704) 892-8600		Coastal (East of I-95): Yes	
P.O. Box 2040		Fax (704) 892-8711		Central (West of I-95 and East of I-77): Yes	
20468 Chartwell Center Dr Cornelius, NC 28031	W	ebsite precisiontankservice.com		Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	·	Yes
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	10/5/2015	Area of state conducts work	
Progress Environmental, Inc.		Phone (336) 722-9999		Coastal (East of I-95): Yes	
120 Fayette Street		Fax (336) 722-9998		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27101		(****)		Mountains (West of I-77): Yes	
	W	ebsite <u>www.progressenvironmental.com</u>		mountains (West of 1-77). Tes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:					
Corrosion Protection Design Experts.	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection Design Experts. Corrosion Protection System Repairs:	No No	Spill Prevention Equipment Testing: Tank Tightness Testing:	No No		No No
Corrosion Protection System Repairs: Corrosion Protection System Testing:				UST Equipment Installation - Other: UST Equipment Repair:	
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No nvironmenta	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No No No No nvironmenta No Yes	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No nvironmenta No Yes	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Protective Technologies, Inc.		Phone (803) 424-0412		Coastal (East of I-95): Yes	
711 Mill Street		Fax (803) 424-0414		Central (West of I-95 and East of I-77): Yes	
Camden, SC 29020		Waltania a waxay waata shi yata ahaa ahaa la wixa iya a aya		Mountains (West of I-77): Yes	
	V	Vebsite www.protectivetechnologiesinc.com			
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
_					
Company		Listing Submitted	9/15/2015	Area of state conducts work	
		Phone (336) 335-3174	9/15/2015	Area of state conducts work Coastal (East of I-95): Yes	
Company Pyramid Environmental & Engineering PC 503 Industrial Ave			9/15/2015		
Company Pyramid Environmental & Engineering PC		Phone (336) 335-3174 Fax (336) 691-0648	9/15/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Pyramid Environmental & Engineering PC 503 Industrial Ave	V	Phone (336) 335-3174	9/15/2015	Coastal (East of I-95): Yes	
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone (336) 335-3174 Fax (336) 691-0648	9/15/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com	9/15/2015 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp	oliance Test	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing:	No	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Yes Yes	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes Yes	Phone (336) 335-3174 Fax (336) 691-0648 Vebsite www.pyramidenvironmental.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Listing Submitted 8/26/2015 Area of state conducts work			UST Service Provider List ((All)		
PO Bob 492 3933 Will Car Road Williamston, NC 27892 Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Overfill Prevention Equipment Operability Check: No Overfill Prevention Sequipment Operability Check: No Operation Design Experts: No Spill Prevention Equipment Testing: No Statistical Neurology Reconcillation Services: No Spill Prevention Design Experts: No Spill Prevention Equipment Testing: No UST Internal Line Leak Detector Equipment Service Contractors Corrosion Protection System Repairs: No UST Internal Line Leak Detector Design Experts: No UST Internal Line Leak Detector Design Experts: No UST Internal Line Leak Detector Design Experts: No UST Internal Line Leak Detector Equipment Repairs: No UST Internal Line Leak Detector Equipment Operability Check: No UST Internal Line Leak Detector Equipment Operability Check: No UST Equipment Repairs: No UST System Installation - Complete Systems: No UST System Removal: U	Company		,	`	Area of state conducts work	
Spass Williamston, NC 27892 Website Webs	RES, Inc		Phone (252) 809-3608		Coastal (East of I-95): Yes	
Mountains (West of 1-77): No Compliance Testing and Monitoring UST Equipment Service Contractors No Overfill Prevention Equipment Operability Check: No Leak Detection Eaging Experts: No Split Prevention Equipment Toesting: No Overfill Prevention Equipment Toesting: No UST internal Inspections (Integrity Assessments): No UST internal Inspections (Integrity Assessments): No UST Equipment Installation Complete Repair: No UST Equipment Repair: No UST			Fax		Central (West of I-95 and East of I-77): Yes	
Compilance Testing and Monitoring					Mountains (West of I-77): No	
Automatic Line Lask Detector Tosting: No Overfill Prevention Equipment Operability Check: No Statistical Ventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Line Legation System Servicin System Repairs: No UST Internal Line Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation - Omplete Systems: No UST System Repair: No UST System Removal: UST System Installation - Omplete Systems: No UST System Removal: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Removal: UST System Removal: UST System Removal: UST System Removal: US	Williamston, NC 27692	W	ebsite		mountaine (troot of 111).	
Containment Sump Teating: No Statistical leventory Reconciliation Services: No Spill Prevention Equipment Teating: No Spill Bucket Installation Equipment Repair: No Spill Bucket Installation Equipment Installation Chine: No Corrosion Protection System Repairs: No Tank Trightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Chine: No UST Equipment Repair: No UST Piping Sump Installation: No UST System Installation - Complete Systems: No UST Piping Sump Installation: No UST System Installation - Chine: No Cental (West of I-77): Yes Website www.roysteroil.com **Company** **Com	Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection System Repairs: No Tank Tightness Testing: No USF Equipment Repair: No Leak Detection System Repairs: No USF Internal Lining Inspections (Integrity Assessments): No USF Equipment Repair: No Central Repetation: No USF Equipment Repair: No Central Repair: No Central Repair: No Central Repetation: No Central Repair: No Central Repair: No Central Repair: No Central Repair: No USF Equipment Repair: No No USF Internal Lining Inspections: No USF Equipment Repair: No No USF Internal Equipment Equipment Equipment Perail Repair: No USF Equipment Repair: No No USF Internal Equipment Equipment Equipment Perail Repair: No USF Equipment Repair: No No USF Equ	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corresion Protection System Repairs: No UST Internal Inspections (Integrity Assassments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections (Integrity Assassments): No UST Equipment Repair: No UST System Installation: Complete Systems: No UST Equipment Operability Check: No UST Pipmig/Sump Installation: No UST Equipment Service: No UST Equipment Monitoring Services: No UST Equipment Service Firms Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Profile Consultants: No UST Equipment Service Contractors: No UST Equipment Service Contractors: No UST Equipment Installation Repair: No No Spill Prevention Equipment Operability Check: No UST Equipment Installation Repair: No UST Equipment No No UST Equipment No UST Equipment No No UST Equipment No UST Equipment No No UST Equipmen	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corresion Protection System Testing: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Other: Control Control Control	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No Uther: Volter:	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: Line Tightness Testing:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No		No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Ves Oil and Solvent Recycling: No Other: Company, Inc. Phone (704) 487-6344 PFax (704) 487-7811 PFax (704) 487-7811 PFax (704) 487-7811 Contained Solvent Recycling: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Overfill Prevention Equipment Operability Check: No Corrosion Protection Design Experts: No Other: No Other:	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Verification: No Other: Soil and Water Testing Lab: No Other Company Company Company Company Phone (704) 487-6344 Fax (704) 487-7811 Cost Lafayette St Shelby, NC 28150 Website Www.roysteroil.com Compliance Testing: No Other: Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Other: No Corrosion Protection System Repairs: No Other: Dispenser Meter Repair/Calibration: No Leak Detectorion Equipment Operability Check: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Installation Other: No UST System Repair: No UST Syste	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Clean No Waste Disposal and Treatment: No Other: Company Royster Oil Company, Inc. PO Box 1467 220 S Lafayette St Shelby, NC 28150 Compiliance Testing and Monitoring Automatic Line Leak Detector Testing: No Spill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No UST Internal Line Leak Detection Posigen Experts: No UST Internal Line Leak Detection Posigen Experts: No UST Internal Line Internal Line Internal Line Leak Detection Equipment Operability Check: No UST Internal Line Internal Inspections: No UST Internal Line Internal Line Inspections: No UST Requipment Repair: No UST Equipment Repair: No UST Internal Line Inspections: No UST Internal Line Inspections: No UST Internal Line Inspections: No UST System Removal: UST System Installation - Complete Systems: No UST System Removal: UST System Remov	E	nvironmenta	Il Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Verification: No Other: Other: Company	Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Oil and Solvent Recycling: No No Other: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: No Other: Listing Submitted 9/8/2015 Area of state conducts work Coastal (East of I-95): No Coastal (East of I-95)		No		No		
Company Listing Submitted 9/8/2015 Area of state conducts work	Environmental Engineer/Geologist Soil and GW Cleanu	. No	Waste Disposal and Treatment:	<u>Yes</u>		
Royster Oil Company, Inc. Phone (704) 487-6344 PO Box 1467 720 S Lafayette St Shelby, NC 28150 Website www.roysteroil.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Brevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation - Other: No UST System Removal: Yes Christian State conducts work Central (West of I-95): No Central (West of I-95): No Dispenser Meter Repair (Celipration: No Dispenser Meter Repair/Celibration: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: Yes Other:	Oil and Solvent Recycling:	No	Other:			
Royster Oil Company, Inc. Phone (704) 487-6344 PO Box 1467 720 S Lafayette St Shelby, NC 28150 Website www.roysteroil.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Removal: UST System Removal: No UST System Removal: UST System Removal: No UST System Removal: Vess Temergency Cleanup - Spill/Release: No UST Compliance Consultants: No Other: Waste Disposal and Treatment: No Other:	Soil and Water Testing Lab:	No				
Royster Oil Company, Inc. Phone (704) 487-6344 PO Box 1467 720 S Lafayette St Shelby, NC 28150 Website www.roysteroil.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Internal Lining Inspections (Integrity Assessments): No Leak Detection Equipment Repair: No UST System Installation: No UST System Removal: US	Company		Listing Submitted	9/8/2015	Area of state conducts work	
PO Box 1467 720 S Lafayette St Shelby, NC 28150 Website www.roysteroil.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Bucket Installation Servicing: No Corrosion Protection System Repairs: No UST Internal Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST System R			Phone (704) 487-6344		Coastal (East of I-95); No	
Shelby, NC 28150 Website www.roysleroil.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: Yes UST System Removal: Yes UST System Removal: Yes UST System Removal: No Other: No Other: No UST Ompliance Consultants: No Other: No Other: No Other: No Other:	:		,			
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Brevention Equipment Testing: No Spill Brevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Tespair: No UST System Reposir: No UST System Repairs: No UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: UST Pyping/Sump Installation: No UST System Removal: UST System Removal: UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Testing: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Other: No Other: Waste Disposal and Treatment: No Other:			1 dx (704) 407 7011			
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Ves Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Repair: No UST System Removal: Ves UST System Removal: Ves Other: No UST System Removal: Ves UST System Removal: No UST System Removal: Ves Other: Other: Other: Other: No Other: N	Shelby, NC 28150	W	ebsite <u>www.roysteroil.com</u>		Mountains (west of 1-77): Yes	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: UST System Installation: UST System Installation: UST System Removal: UST System Re	Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Other:	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Repair: No UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: UST System Removal: Other: Description	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Ves Tenvironmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Tenvironmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Other:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Monitoring Services: No Other: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Complete System	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: Ves UST System Removal: Ves Other: UST System Removal: Other: UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Pes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Pes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Other:	Line Tightness Testing:	No				<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	E	nvironmenta	Il Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: No Other:	Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
	Environmental Engineer/Seologist Site Officers.				I .	
Cail and Water Testing Lab.		Yes	Waste Disposal and Treatment:	No		
Soil and Water Testing Lab: No No	Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	· · · · · · · · · · · · · · · · · · ·		No		

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
S&ME, Inc.		Phone 7045234723		Coastal (East of I-95): Yes	
9751 Southern Pine Blvd		Fax 7045253953		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28273	187	abatta www.amaina.aan		Mountains (West of I-77): Yes	
	VV	ebsite <u>www.smeinc.com</u>			
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Eı	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/26/2015	Area of state conducts work	
Company SENSIBLE SOLUTIONS ENVIRONMENTAL			8/26/2015		
		Phone (336) 263-0965	8/26/2015	Coastal (East of I-95): No	
SENSIBLE SOLUTIONS ENVIRONMENTAL			8/26/2015	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074		Phone (336) 263-0965		Coastal (East of I-95): No	
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC	w	Phone (336) 263-0965 Fax		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC	w	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.co		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC	W oliance Testi	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring	<u>om</u>	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Line Leak Detector Testing:	W oliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check:	<u>om</u> No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing:	W Dliance Testi No No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	om No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W Dliance Testi No No No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi No No No No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Woliance Testi No No No No No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Woliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Woliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Woliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Woliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Woliance Testi No	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
SENSIBLE SOLUTIONS ENVIRONMENTAL PO BOX 3074 CHAPEL HILL, NC Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 263-0965 Fax ebsite www.sensible-solutions-environmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Shield Engineering, Inc.		Phone (704) 394-6913		Coastal (East of I-95): No	
4301 Taggart Creek Road		Fax (704) 394-6968		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28208				Mountains (West of I-77): Yes	
	VV	debsite www.shieldengineering.com		,	
Comp	oliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	1 1	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	· ·	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	· · · · · · · · · · · · · · · · · · ·	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		No
Leak Detection Monitoring Services:	No	Other:		1 0 1	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/8/2015	Area of state conducts work	
Simonsen Law Firm, P.C.		Phone (252) 482-2175		Coastal (East of I-95): Yes	
106 E. Queen St.		Fax (252) 482-1355		Central (West of I-95 and East of I-77): Yes	
P.O. Box 848		1 dx (232) 402-1000			
Edenton, NC 27932	W	ebsite www.simonsenlawfirm.com		Mountains (West of I-77): Yes	
Comp	oliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Legal Services related to all UST	issues	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
				1	

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Singleton Environmental, Inc.		Phone (828) 667-5001		Coastal (East of I-95): No	
PO Box 2012		Fax (828) 667-0105		Central (West of I-95 and East of I-77): No	
1301 Sand Hill Road Enka, NC 28728		,		Mountains (West of I-77): Yes	
LINA, INC 20120	W	ebsite <u>www.singletonenvironmental.com</u>			
Comp	oliance Test	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	· · · · · · · · · · · · · · · · · · ·	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No .	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/27/2015	Area of state conducts work	
SouthEastern Petroleum Systems, Inc.		Phone (704) 394-3178	0,21,2010	Coastal (East of I-95): Yes	
101 Lawton Road		,		· · · · · · · · · · · · · · · · · · ·	
Charlotte, NC 28216		Fax (704) 394-3170		Central (West of I-95 and East of I-77): Yes	
,	W	ebsite www.sepsusa.com		Mountains (West of I-77): Yes	
Comp	oliance Test	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No .	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:	-	UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
		I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>res</u> <u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>res</u> No		
Oil and Solvent Recycling:	No	Other: Tank Cleaning and Biocide Trea			
Soil and Water Testing Lab:	No	Talk Oleaning and biocide free	attiletite		
Our and Water Testing Lab.	NO				

		UST Service Provider List	(All)		
Company		Listing Submitte		Area of state conducts work	
SR&R Environmental, Inc.	ı	Phone (910) 763-6274		Coastal (East of I-95): Yes	
49220 Highway 421 N.		Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	
PO Box 221 Wilmington, NC 28402	147			Mountains (West of I-77): Yes	
	VVE	ebsite <u>www.srrenviro.com</u>			
Comp	liance Testii	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other: Vacuum Truc	k Service		
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 8/27/2015	Area of state conducts work	
Company Superior Services	ı	Listing Submitter Phone (828) 698-6286	8/27/2015	Area of state conducts work Coastal (East of I-95): Yes	
Superior Services PO Box 982	i	Phone (828) 698-6286	d 8/27/2015	Coastal (East of I-95): Yes	
Superior Services	I		d 8/27/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Superior Services PO Box 982		Phone (828) 698-6286	d 8/27/2015	Coastal (East of I-95): Yes	
Superior Services PO Box 982 Hendersonville, NC 28793	We	Phone (828) 698-6286 Fax (828) 698-6294	d 8/27/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Superior Services PO Box 982 Hendersonville, NC 28793	We	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Ebsite www. superiorservices.us	8/27/2015 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Superior Services PO Box 982 Hendersonville, NC 28793 Comp	We bliance Testin Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6294		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Superior Services PO Box 982 Hendersonville, NC 28793 Compa	We bliance Testin Yes Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6286 Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6286 Phone (828) 698-6294 Phone (<u>Yes</u>	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Superior Services PO Box 982 Hendersonville, NC 28793 Compart Automatic Line Leak Detector Testing: Containment Sump Testing:	We bliance Testin Yes Yes Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6286 Phone (828) 698-6294 Phone	<u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Superior Services PO Box 982 Hendersonville, NC 28793 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Webliance Testin Yes Yes Yes Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	<u>Yes</u> No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Webliance Testing Yes Yes Yes Yes Yes Yes Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6286 Phone (828) 698-6286 Tax (828) 698-6286 Phone (828) 698-6286 Fax (828) 698-6286 Phone (828) 698-6286 Fax (828) 698-6286 Phone (828) 698-6294 Phone (828	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 698-6286 Fax (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6294 Phone (828) 698-6286 Fax (828) 698-6286 Phone (828) 698-6294 Phon	Yes No Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Compariation Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 698-6286 Fax (828) 698-6294 Pebsite www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 698-6286 Fax (828) 698-6294 Pebsite www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes No Yes	Phone (828) 698-6286 Fax (828) 698-6294 Phone www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Repairs, AST inspection, testing	Yes No Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes No Yes No Yes No No No	Phone (828) 698-6286 Fax (828) 698-6294 Posite www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Repairs, AST inspection, testings	Yes No Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Compart Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Ves Yes Yes Yes Yes Yes Yes Yes No Yes No Yes No No No	Phone (828) 698-6286 Fax (828) 698-6294 Phosite www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Repairs, AST inspection, testing Service Firms UST Compliance Consultants:	Yes No Yes Yes Yes Yes ng, repair	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Superior Services PO Box 982 Hendersonville, NC 28793 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes Yes Yes Yes Yes Yes Yes No Yes No No No No	Phone (828) 698-6286 Fax (828) 698-6294 Phosite www. superiorservices.us Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Repairs, AST inspection, testing Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes Yes Yes Yes ng, repair	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List	(AII)		
Company		Listing Submitted		Area of state conducts work	
Terracon Consultants, Inc.		Phone (704) 509-1777		Coastal (East of I-95): Yes	
2020 Starita Road		Fax (704) 509-1888		Central (West of I-95 and East of I-77): Yes	
Suite E Charlotte, NC 28206				Mountains (West of I-77): Yes	
Chanotte, NO 20200	W	ebsite <u>www.terracon.com</u>		,	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	9/3/2015	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street		Fax (919) 563-9095		Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302		(0.0) 000 000		Mountains (West of I-77): Yes	
	W	ebsite <u>www.terraquestpc.com</u>		wountains (west of 1-77). Tes	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Oil and Solvent Recycling: Soil and Water Testing Lab:	No No	Other:			

		UST Service Provider List	(AII)		
Company		Listing Submitte		Area of state conducts work	
The Clark Group dba Clark Environmental Serv P.O. Box 10136 4918 Wrightsville Avenue Wilmington, NC 28404		hone (910) 392-5555 Fax (910) 392-5552 bsite www.clarkgroup.us		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Comp	liance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling: Soil and Water Testing Lab:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: Vaste Disposal and Treatment: Other:	No No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: Other:	No No No No No No Yes
Company		Listing Submitted	d 9/9/2015	Area of state conducts work	
The El Group, Inc. 2101 Gateway Centre Boulevard Suite 200 Morrisville, NC 27560		hone (919) 657-7500 Fax (919) 657-7551		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Comp	liance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No S No S No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: Vaste Disposal and Treatment: Other:	No No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: Other:	No No No No No No Yes

		UST Service Provider List (AII)		
Company		Listing Submitted	9/9/2015	Area of state conducts work	
The El Group, Inc.		Phone (919) 657-7500		Coastal (East of I-95): Yes	
2101 Gateway Centre Boulevard		Fax (919) 657-7551		Central (West of I-95 and East of I-77): Yes	
Suite 200 Morrisville, NC 27560		. ,		Mountains (West of I-77): Yes	
Wornsville, NC 27300	١	Vebsite			
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/29/2015	Area of state conducts work	
TideLand Construction, LLC		Phone (252) 375-8787		Coastal (East of I-95): Yes	
1006 Wall Street				· · · · · · · · · · · · · · · · · · ·	
Greenville, NC 27858		Fax		Central (West of I-95 and East of I-77): Yes	
	V	Website tidelandconstruction.com		Mountains (West of I-77): No	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List (AII)		
Company		Listing Submitted		Area of state conducts work	
TideLand Construction, LLC		Phone (252) 375-8787		Coastal (East of I-95): Yes	
1006 Wall Street		Fax (252) 355-3932		Central (West of I-95 and East of I-77): Yes	
Greenville, NC 27858		,		Mountains (West of I-77): No	
	1	Website tidelandconstruction.com			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/29/2015	Area of state conducts work	
Tidewater fuel distribution services		Phone (910) 376-4584		Coastal (East of I-95): Yes	
511 Myna Drive		Fax		· · · · · · · · · · · · · · · · · · ·	
Jacksonville, NC 28540		rax		Central (West of I-95 and East of I-77): No	
	1	Website		Mountains (West of I-77): No	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List	(All)		
Company		Listing Submitted	9/2/2015	Area of state conducts work	
UST Corrosion Management, Inc.	rosion Management, Inc. Phone (888) 822-2431			Coastal (East of I-95): Yes	3
2764 Pleasant Rd. #10714	Fax (803) 802-0561			Central (West of I-95 and East of I-77): Yes	3
Fort Mill, SC 29708	Wel	osite www.ustcorrosion.com		Mountains (West of I-77): Yes	3
Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	Yes 7	ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No L	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No L	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No L	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	/aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No (Other:			
Soil and Water Testing Lab:	No				